Oil Field Environmental Incident Summary

Date/Time of Notice: 03/03/2016 09:56 Incident: 20160303095630 Responsible Party: RIM OPERATING, INC. Well Operator: RIM OPERATING, INC. Well Name: MESA 13-29H Field Name: LAKESIDE Well File #: 16867 Date Incident: 3/3/2016 Time Incident: 08:00 Facility ID Number: **BURKE Twp:** 163 Sec: 29 Qtr: County: **Rna**: 89 Location Description: Submitted By: Liz Ortiz Received By: Scott Kalmbach Contact Person: **5 INVERNESS DRIVE EAST** ENGLEWOOD, CO 80112 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil 1 Mile **Distance Nearest Occupied Building:** Distance Nearest Water Well: 1 Mile Type of Incident: Equipment Failure Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No **Units** Recovered Units Spilled **Followup Units** Oil **Brine Barrels Barrels** barrels Other **Description of Other Released Contaminant:** none Inspected: Written Report Received: 3/16/2016 Clean Up Concluded: 3/4/2016 Risk Evaluation: none

Friday, February 10, 2017 Page 1 of 2

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

fire tube was repaired

Wastes Disposal Location: vac truck recovered the water and placed in water tank on location

Agencies Involved:

Updates

Date: 3/4/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. NDIC has oversight.